

NTSB National Transportation Safety Board

Office of Aviation Safety



Chalk's Ocean Airways G-73T Seaplane

Port of Miami, Florida December 19, 2005





NTSB 😻

Right Wing Separated





Accident Information

- 2 crew, 18 passengers fatal
- Major go-team assembled
- Chairman Rosenker on scene



History

- Chalk's began service in 1919
- Chalk's used Mallards since 1970s
- Accident airplane built in 1947
- 31,000 hours, 40,000 cycles



Wing Failure

- Preexisting fatigue cracks
- Not effectively identified/repaired
- Did not correct underlying damage
- Led to failure of wing





Safety Issues

- Maintenance program and practices
- FAA oversight of maintenance
- Aging Aircraft Regulations



Parties to the Investigation

- Federal Aviation Administration
- Chalk's Ocean Airways
- Frakes Aviation
- Hartzell Propellers
- Grumman Mallard Owners Association



Accredited Representatives

- Transportation Safety Board of Canada
 - Transport Canada
 - Pratt & Whitney Canada
- Bahamas Ministry of Transport



Other Agencies

- U.S. Coast Guard
- Federal Bureau of Investigation
- Miami Beach Police
- Australian Transport Safety Bureau



Further Presentations

- Laboratory examination
- Chalk's maintenance and FAA oversight
- Aging aircraft safety regulations





NTSB